


Service Bulletin #: AC-040709
Date: 7 April 2009
Models Affected: AS350, AS355, EC130
Compliance: REQUIRED FOR PROPER FREON SERVICING

This Service bulletin has been issued to any operator of Integrated Flight Systems air conditioning system installed on the following aircraft; Eurocopter AS350, AS355 & EC130.

The intent of this service bulletin is to bring up to date Freon servicing instruction for systems already installed.

A placard has been made to show the proper amount of Freon required for servicing.

This new data shown in the placard reflects the latest info on servicing now being sent with our kits. Disregard any previous servicing instructions, and follow the placards data.



If sticker is needed please contact I.F.S. at 1-817-624-6600, order P/N: 120214.

Engineering Approval:

Signature Michael Diabman Qualification: Technical Service Support

Date: 04/07/09